



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER

Executive Director

JOHN R. BAZA

Division Director

Inspection Report

Minerals Regulatory Program

Report Date: August 31, 2006

Supervisor _____

Mine Name: Blowout/First Chance

Operator Name: Rex Claridge

Permit number: S0230039

Inspection Date: 08/29/2006

Inspector(s): Dan Smith

Other Participants: None

Mine Status: ACT

Weather: No adverse conditions affecting site visit.

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other			

Purpose of Inspection:

Data base indicates this site has been active in previous years but never been inspected.

Directions to Site:

Easy access to site. See map.

Inspection Summary:

No signs of recent activity.

Conclusions and Recommendations:

Recommend that the primary inspector review this mine permit.

Inspector's Signature

Daniel Smith

Date: August 31, 2006

ds

cc: Operator

Attachment: Map & Photos





